



Service checking the history of the car by VIN code

carvin-info.com

FULL CHECK



Technical characteristics of the vehicle:

VIN:	WBANC91070*****
Vehicle Type:	Passenger car
Brand:	BMW
Country of origin:	Germany
Type:	NC91
Production date:	2006-05-08
Model code:	E60
Model:	535D (EUR)
Body type:	Sedan, 4 doors (Lim)
Engine:	M57X
Displacement, l:	3.00
Power, KW:	200
Gearbox:	Automatic (AUT)
Drivetrain:	Rear-wheel drive (HECK)
Steering:	Left hand drive (LL)
Body colour:	CARBONSCHWARZ METALLIC (416)
Upholstery:	LEDER DAKOTA/SCHWARZ (LCSW)

Standard equipment, custom options:

S534A	Automatic air conditioning (KLIMAAUTOMATIK)
S548A	Kilometre speedo (KILOMETERTACHO)
S851A	Language version German (SPRACHVERSION DEUTSCH)






S2NNA	BMW alloy wheel, M double spoke 172 (M LM R.DOPPELSP.172 M/MISCHB.)	
S205A	Automatic transmission (AUTOMATIC GETRIEBE)	
S217A	Active steering (AKTIVLENKUNG)	
S261A	Side airbags for rear passengers (SEITENAIRBAG FUER FONDPASSAGIERE)	
S300A	Emergency spare wheel (NOTRAD)	
S302A	Alarm system (ALARMANLAGE)	
S320A	Deleted, model lettering (MODELLSCHRIFTZUG ENTFALL)	
S322A	Comfort access (KOMFORTZUGANG)	
P337A	M Sports package (M SPORTPAKET)	
S403A	Glass roof, electrical (GLASDACH, ELEKTRISCH)	
S415A	Sun-blind, rear (SONNENSCHUTZROLLO FUER HECKSCHEIBE)	
S416A	Roller sun visor, rear lateral (SONNENSCHUTZROLLOS)	
S423A	Floor mats velours (FUSSMATTEN IN VELOURS)	
S428A	Warning triangle and first aid kit (WARNDREIECK)	
S431A	Interior mirror with automatic-dip (INNENSPIEGEL,AUTOMATISCH ABBLENDEND)	
S437A	Fine wood trim (EDELHOLZAUSFUEHRUNG)	
S441A	Smoker package (RAUCHERPAKET)	
S442A	Drink holder (GETRAENKEHALTER)	
S456A	Comfort seat with memory (KOMFORTSITZE ELEKTRISCH VERSTELLBAR)	
S465A	Through-loading system (DURCHLADESYSTEM)	
S494A	Seat heating driver/passenger (SITZHEIZUNG FUER FAHRER/BEIFAHRENER)	
S496A	Seat heating, rear (SITZHEIZUNG FUER FONDSITZE)	
S5ACA	High-beam assistant (FERNLICHTASSISTENT)	
S502A	Headlight cleaning system (SCHEINWERFER-WASCHANLAGE)	
S508A	Park Distance Control (PDC) (PARK DISTANCE CONTROL (PDC))	

S522A	Xenon Light (XENON-LICHT)	
S524A	Adaptive Headlights (ADAPTIVES KURVENLICHT)	
S541A	Active cruise control (AKTIVE GESCHWINDIGKEITSREGELUNG)	
S563A	Light package (LICHTPAKET)	
S6AAA	BMW TeleServices (BMW TELESERVICES)	
S601A	TV function (TV-FUNKTION)	
S609A	Navigation system Professional (NAVIGATIONSSYSTEM PROFESSIONAL)	
S610A	Head-up display (HEAD-UP DISPLAY)	
S611A	BMW Night Vision (BMW NIGHT VISION)	
S612A	BMW Assist (BMW ASSIST)	
S616A	BMW Online (BMW ONLINE)	
S620A	Voice control (SPRACHEINGABESYSTEM)	
S633A	Preparation, mobile phone, Business (HANDY VORB. BUSINESS/BLUETOOTH-SCH.)	
S672A	CD changer for 6 CDs (CD WECHSLER 6-FACH)	
S676A	HiFi speaker system (HIFI LAUTSPRECHERSYSTEM)	
S698A	Area-Code 2 for DVD (AREA-CODE 2)	
P7R7A	Innovation package (INNOVATIONSPAKET)	
S704A	M Sports suspension (M SPORTFAHRWERK)	
S710A	M leather steering wheel (M LEDERLENKRAD)	
S715A	M Aerodynamics package (M AERODYNAMIKPAKET)	
S754A	M Rear spoiler (M HECKSPOILER)	
S760A	High gloss shadow line (INDIVIDUAL HOCHGLANZ SHADOW LINE)	
S775A	Headlining anthracite (INDIVIDUAL DACHHIMMEL ANTHRAZIT)	
S8SAA	Navigation access request,country-spec. (LAENDERSPEZ. NAVI.-FREISCHALTUNG)	
S8SPA	Control unit COP (COP STEUERUNG)	
L801A	National version Germany (DEUTSCHLAND-AUSFUEHRUNG)	

	S863A	Dealer List Europe (SERVICE KONTAKT-FLYER EUROPA)	
	S879A	On-board literature, German (DEUTSCH / BORDLITERATUR)	
	S934A	Dummy-SALAPA (WINTERREIFEN AUF LM-RAEDER)	
	S936A	Dummy-SALAPA (BMW HANDY BEI AUSLIEF. ANFORDERN)	
	S964A	Navi DVD to be requested at shipping (REQUEST NAVIG. DVD ON DELIVERY)	
	Parameter	Value	
	DB storage version:	2.0	
	Data language:	en	
	Record was added in database:	2018-12-22 1:05	
	Last query date:	2018-12-23 13:55	
	Last update date:	2018-12-22 1:05	
	Data display version:	2.0	
	Manufacturer's data version:	2.36 12/2018 from 2018-11-27	

The presence of encumbrances, restrictions:

	More than 80 sources were used to verify the VIN number, including:		
		National Insurance Crime Bureau (NICB);	
		National Vehicle Information System (NMVTIS);	
		Police base of stolen cars in France;	
		Police base of stolen cars in Germany;	
		Police base of stolen cars in Hungary;	
		Police base of stolen cars in Italy;	
		Police base of stolen cars in Lithuania;	
		Police base of stolen cars in Poland;	
		Police base of stolen cars in the Czech Republic;	
		Register of the Ministry of Internal Affairs of Ukraine	

		State Automobile Inspectorate of the Russian Federation;	
		The base of stolen cars in Norway;	
		The base of stolen cars in Romania;	
		The base of stolen cars in Slovenia;	
		The base of stolen cars in Sweden;	
		The base of stolen cars in the Netherlands.	
	Car arrest:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
	Car rental:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
	Car pledged:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
	Car loan:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
	Car stolen:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
	22.11.2014	Car theft was fixed in Italy in the city of Rome	
	Restrictions on registration actions:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
	According to the results of checking the car by VIN number: 11/22/2014 - car theft was fixed; the presence of other encumbrances or any restrictions on the day of inspection is not revealed		
Information about participation in the accident:			
	22.11.2015 22:06	A collision was recorded on the territory of Italy in the city of Sicily	
	16.05.2016 18:07	A collision was recorded on the territory of Italy in the city of Rome	
	During the operation recorded 2 crashes		

Last officially recorded mileage:**14.01.2018****195 530 km****Average mileage of cars of this model and the same age:****156 400 km****The history of the mileage:**

	Date	Mileage (km)	Dealer
	03.02.2017	184 038	04947/01
	06.01.2015	160 878	04947/01
	05.01.2015	160 863	04947/01
	13.11.2014	156 780	04947/01
	02.10.2014	153 983	04947/01
	15.09.2014	152 660	04847/02
	21.12.2012	136 690	28150/01
	13.08.2012	127 461	22321/02
	13.02.2012	114 303	22321/02
	04.10.2011	104 431	22321/02
	02.10.2010	89 520	22321/02
	05.06.2009	56 400	22321/02
	05.08.2008	29 560	22321/02

**No discrepancies in the mileage were found, the mileage on the odometer was not twisted****The history of repairs, maintenance:**

Date of event	Code working position / Code parts	Description	Amount
27.11.2017	139 912 km		
		Service consultations for a car with a service coupon	0

		Calibration of the KAFAS camera	1
		Performing a car check	2
		Replacing the windshield	24
		Additional operation with rain/light intensity sensor	3
	83192289285	Repair kit, window glass, cold, 1 hour	1,0
	51137258183	Clip, drip moulding	10,0
	51317288462	Bump stop	11,0
	83192211217	Cleaner R1	1,0
	51487325890	Sound insulation f apron	1,0
	51437321215	Clamp	2,0
	51317258072	Windscreen, green, rain sensor / HUD	1,0
	51317258053	Cover, windshield, top	1,0
		FEINSTAUBPLAKETTE GRÜN	1
		Vacuum the vehicle without charge	2
		<i>Engine oil service</i>	
		Maintenance according to the regulations Oelservice	3
	11428575211	Set oil-filter element	1,0
		<i>Service - stadard scope</i>	
		Maintenance in the usual scope	2
		<i>Service - micro filter/activated carbon filter</i>	
		Maintenance "Microfilter"	2
	64119237555	Microfilter/activated Carbon container	1,0
		<i>Service - vehicle check</i>	
		Maintenance "Car diagnostics"	

		<i>Service - fuel filter</i>	6
24.11.2017	139 912 km		
		Replacing both wiper blades	1
	61612241375	Set of wiper blades	1,0
13.10.2017	131 510 km		
		Engine oil service	0
		Execution of a plan for checking and updating a manual transmission	8
		Checking the car as part of the acceptance	0
		Replacing four tires with Runflat technology	33
		Mount winter wheels, Mount the summer wheels	6
		Weights	8
		Tire storage for tire storage	1
		Vacuum the vehicle without charge	2
28.03.2017	98 167 km		
		Removing and installing front and rear wheels	3
15.02.2017	87 983 km		
		Maintenance in the usual scope	2
		Removing and installing / replacing brake discs front wheels	3
		Maintenance "Front brakes"	6
	34106859181	Repair kit, brake pads asbestos-free	1,0
	34211161806	Inner hex bolt	2,0
	34116792219	Brake disc, ventilated	2,0
	83192158851	Brake-pad paste	2,0

	34356792289	Brake pad wear sensor, front left	1,0
		Maintenance "Rear brakes"	7
	34356792292	Brake-pad sensor, rear	1,0
	34216873093	Repair kit, brake pads asbestos-free	1,0
	83192158851	Brake-pad paste	2,0
09.11.2016	66 353 km/07466		
		Service - stadard scope	
		Maintenance in the usual scope	2
		Engine oil service	
		Maintenance according to the regulations Oelservice	3
	11428575211	Set oil-filter element	1,0
		<i>Service - micro filter/activated carbon filter</i>	
		Maintenance "Microfilter"	2
	64119237555	Microfilter/activated Carbon container	1,0
		Service - air cleaner	
		Maintenance of the replaceable element of the air filter	2
	13718511668	Air filter element	1,0
		Service - fuel filter	
		Maintenance of the fuel filter	3
	07129952104	Hose clamp	1,0
	13328572522	Fuel filter cartridge	1,0
		Service - vehicle check	

		Maintenance "Car diagnostics"	6
03.06.2016	32 475 km		
		Service - stadard scope	
		Maintenance in the usual scope	2
		Engine oil service	
		Maintenance according to the regulations Oelservice	3
	11428575211	Set oil-filter element	1,0
		<i>Service - micro filter/activated carbon filter</i>	
		Maintenance "Microfilter"	2
	64119237555	Microfilter/activated Carbon container	1,0